

ENERGY STAR[®] Statement of Energy

Performance



DPW Garage

Primary Property Type: Other - Public Services Gross Floor Area (ft²): 20,000 Built: 2018

ENERGY STAR® Score¹

For Year Ending: December 31, 2018 Date Generated: April 24, 2019

1. The ENERGY STAR score is a 1-100 assessment of a building's energy efficiency as compared with similar buildings nationwide, adjusting for climate and business activity.

Property & Contact Information				
Property Address	Property Owner	Primary Contact		
DPW Garage	Village of Croton-on-Hudson	Bryan Healy		
435 Yorktown Road	1 Van Wyck Street	1 Van Wyck Street		
Croton-on-Hudson, New York 10520	Croton-on-Hudson, NY 10520	Croton on Hudson, NY 10520		
	9142714848	9142714848		
		bhealy@crotononhudson-ny.gov		

Property ID: 6810151

Energy Consumption and Energy Use Intensity (EUI)

Site EUI	Annual Energy by Fuel	National Median Comparison	
30.7 kBtu/ft ²	Electric - Grid (kBtu) 194,484 (32%)	National Median Site EUI (kBtu/ft ²)	56.6
30.7 KDIU/II-	Fuel Oil (No. 2) (kBtu) 418,996 (68%)	National Median Source EUI (kBtu/ft ²)	89.3
		% Diff from National Median Source EUI	-46%
Source EUI		Annual Emissions	
48.4 kBtu/ft ²		Greenhouse Gas Emissions (Metric Tons CO2e/year)	48

Signature & Stamp of Verifying Professional

I _____ (Name) verify that the above information is true and correct to the best of my knowledge.

Signature: _____Date: _____

Licensed Professional

__)___--



Professional Engineer Stamp (if applicable)