



# ENERGY STAR<sup>®</sup> Statement of Energy Performance

# N/A

## DPW Garage

**Primary Property Type:** Other - Public Services  
**Gross Floor Area (ft<sup>2</sup>):** 20,000  
**Built:** 2018

**ENERGY STAR<sup>®</sup>**  
**Score<sup>1</sup>**

**For Year Ending:** December 31, 2022  
**Date Generated:** July 18, 2023

1. The ENERGY STAR score is a 1-100 assessment of a building's energy efficiency as compared with similar buildings nationwide, adjusting for climate and business activity.

### Property & Contact Information

**Property Address**

DPW Garage  
435 Yorktown Road  
Croton-on-Hudson, New York 10520

**Property Owner**

\_\_\_\_\_  
,  
(\_\_\_\_)\_\_\_\_-\_\_\_\_

**Primary Contact**

Bryan Healy  
1 Van Wyck Street  
Croton on Hudson, NY 10520  
9142714848  
bhealy@crotononhudson-ny.gov

**Property ID:** 6810151

### Energy Consumption and Energy Use Intensity (EUI)

**Site EUI**

30.2 kBtu/ft<sup>2</sup>

**Annual Energy by Fuel**

Electric - Grid (kBtu) 167,597 (28%)  
Fuel Oil (No. 2) (kBtu) 437,184 (72%)

**National Median Comparison**

National Median Site EUI (kBtu/ft<sup>2</sup>) 59.3  
National Median Source EUI (kBtu/ft<sup>2</sup>) 89.3  
% Diff from National Median Source EUI -49%

**Source EUI**

45.5 kBtu/ft<sup>2</sup>

**Annual Emissions**

Total (Location-Based) GHG Emissions 47  
(Metric Tons CO<sub>2</sub>e/year)

### Signature & Stamp of Verifying Professional

I \_\_\_\_\_ (Name) verify that the above information is true and correct to the best of my knowledge.

LP Signature: \_\_\_\_\_ Date: \_\_\_\_\_

#### Licensed Professional

\_\_\_\_\_  
,  
(\_\_\_\_)\_\_\_\_-\_\_\_\_  
\_\_\_\_\_



**Professional Engineer or Registered  
Architect Stamp  
(if applicable)**